

Wireless Data Loggers XpertLog[®]

Ultra Low Temperature Applications & Accessories



Wireless Logger for Ultra Low Temperature

Temperature range: -80 to 100 °C



Ultra Low Temperature Dry Block

Temperature range: -90 to 125 °C



Freeze Dryer & SIP Wireless Logger

Temperature range: -60 to 140 °C



Freeze Dryer Shelf Mapping

Temperature range: -60 to 140 °C



**USB Docking Station for
Wireless Data Loggers**



Applications :

- Freeze dryers
- Incubators
- Stability Chambers
- Cold rooms
- all application within the range of temp -80 to 100 °C



- Automatic Calibration & Verification
- Automatically Reports Generation
- Technical support 24/7